

QPPCN

Release Date: November 20, 1995 Expiration Date: November 1996

CN 799DR: Authorization and Disposition of Expense

CUSTOMER INFORMATION MANAGEMENT SYSTEMS SYSTEM 75®R1V3n CLASS QC CHANGE (Software R1V3 Issue 3.5)

.

11900 North Pecos St. Denver, Colo. 80234 November 20, 1995

This Change Notice is for System 75®R1V3 customers HCMR format tape. PG65330-01 Issue 3.5 R1V3A.b9.15 contains changes as described in the Change Information Errata Sheet section of this change notice.

The Change Notice supersedes 743DR.

Issue 3.5 (R1V3a.b9.15) is NOT intended to applied to all System 75O R1V3 systems. It applies only to systems with problems corrected by this release, see Information Errata Sheet section and verified by Tier III.

NANP The North American Numbering Plan is included in this software load. However; it is not activated and should not be unless purchased by the customer.

Customers that require a new tape for maintenance reasons shall upgrade all tapes in the switch to Issue 3.5.

BILLING INFORMATION

This change requires service to be interrupted and shall be implemented on a no charge basis to all qualified customers under warranty, lease or maintenance contract. T&M customers will be billed for labor using SPE 0206-900.

COORDINATION

Coordination is not required with any other QPPCN.

REASON FOR CHANGES

Reasons for this change are summarized in the Change Information Errata Sheet.

DETAILS OF CHANGE

Details are defined in the sections of this change notice listed below:

- ORDERING REQUIREMENTS
- AUTHORIZATION
- SUMMARY
- SOFTWARE UPGRADE PROCEDURES
- SOFTWARE CONFIGURATION
- SPECIAL PROCEDURES
- CHANGE INFORMATION ERRATA SHEET
- QPPCN 799DR CUSTOMER INFORMATION SHEET

ORDERING REQUIREMENTS

Material for this Change Notice shall be managed by the TSC Change Notice Coordinator.

<u>SYSTEM QTY</u> <u>CODE</u> <u>DESCRIPTION</u> <u>ISSUE</u> System 75 HCMR 2 J58890TC, L1 Tape Cartridge, PG-65330 Issue 3.5

Refer all administrative questions pertaining to this Change Notice to your local Marketing Branch

SOFTWARE CONFIGURATION

The following table contains the software vintage numbers which are obtained when performing a "list configuration software" at the SAT. This should be used to verify what release is installed on a machine.

Issue	Software Vintage	Internal Release	Patched Vintage
R1V1			
1.2 1.3 1.4 1.5 1.6	3427 4126 4358 4364 4416	R1L1B.f2.35 R1L1C.a1.30 R1L1C.b1.6 R1V1C.b1.12 R1V1C.b2.0	4359 4365
R1V2 XE			
1.0 1.1 1.4 1.5	14346 14347 14351 14356	R1V1D.a1.10 (AKA JR20) R1V1D.a1.11 (AKA JR21) R1V2D.a1.15 (AKA JR25) R1V2D.a1.20 (AKA JR30)	14357 14361
R1V2			
1.0 1.1 1.2 1.3 1.4 1.5	8215 8218 8224 8326 8389 8453	R1V2A.a1.23 R1V2A.a1.26 R1V2A.a1.32 R1V2A.a3.6 R1V2A.a4.5 R1V2A.b1.5	8225 8327 8390
R1V3			
1.0 1.1 1.2 1.3 1.4 1.5 1.6 1.7 2.0 2.1	16643 16675 16962 16966 17026 17028 17060 17062 17123 17153	R1V3A.a9.3 R1V3A.a10.3 R1V3A.b3.2 R1V3A.b3.6 R1V3A.b5.2 R1V3A.a5.4 R1V3A.b6.4 R1V3A.b6.6 R1V3A.b8.3 R1V3A.b9.1	16676

Note: Any tape not corresponding to an official issue should be upgraded to the most recent issue.

^{*} The "patched vintage" applies to systems that have been patched with the TN742 maintenance change. The patch is not necessary in the R1V1 Issue 1.6, R1V2 Issue 1.5 (standard and XE) or the R1V3 Issues beginning with 1.2.

QPPCN 799DR----CUSTOMER INFORMATION SHEET

- Previously, customers in Overlay and Metro-Extended Local NPA area could not complete both 7 and 10-digit calls. Both 7 and 10 digit calls will now complete in this scenario.
- Previously, When a customer experienced a reset sys 4 or power outage, processor channels did not come back up. The processor channels will now come up in a functioning mode after a reset system 4 or power outage.
- Previously, the Emergency Attendant Access feature could tie up the attendant console. This is no longer the case.