



NUMBER: 23-011-04

GROUP: Body

DATE: April 20, 2004

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Bug Deflector Loose/Rattling

OVERVIEW:

This bulletin involves replacing the bug deflector fasteners.

MODELS:

2003 - 2004 (DR) Ram Truck

NOTE: This Bulletin Applies To Vehicles Equipped With A Factory Installed Bug Deflector, Sales Code MXB.

SYMPTOM/CONDITION:

The bug deflector or air dam located on the front of the hood may become loose and rattle. The deflector could become dislodged in an automatic car wash.

DIAGNOSIS:

If the condition is present, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
6	06508197AA	Fastener

REPAIR PROCEDURE:

Remove the original fasteners and install new fasteners, p/n 06508197AA.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
23-02-02-91	Fasteners, Replace	0.2 Hrs.

FAILURE CODE:

K4	Loose
----	-------