

**Panasonic**  
Communication Systems Division  
Technical Advisory

Updated: Nov. 16, 00

**Subject: SDN Keys Copy Precautions**

**Document Number: KXTD5000003**

**COPY FUNCTION – DO NOT COPY SDN KEYS**

When executing a 'copy' function for the CO key mapping in "Extension Line" program screen, DO NOT COPY SDN KEYS. Copying PDN and SDN Appearances can corrupt the station data because of a conflict when assigning a SDN of your own PDN. This causes a failure at the PT's.